E

Notification of azardous Waste Site



United States Environmental Protection Agency Washington DC 20460

required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981:

Please type or print in ink. If you need


NJS 000 001 397

be maned by dune o, 1001.		•		
	HARS	HAW CHEMICAL CO.		
Person Required to Notify:	None CI DI			
Enter the name and address of or organization required to notif	hv	Name GLOUCESTER CITY PLANT		
or organization roquirou to notif	Street -00	F OF WATER ST.		
	City GLOUC	ESTER CITY State NJ Zip Code 08030		
Site Location:	HARS	SHAW CHEMICAL CO.		
Enter the common name (if kno	wn) and Name of Site GL	Name of Site GLOUCESTER CITY PLANT		
actual location of the site.		Street FOOT OF WATER ST.		
NJD 000 312	371 City & LOUCE STE	City G LOUCE STER COUNTY GLOUCESTERIE NJ Zip Code 0 8030		
Person to Contact:				
Enter the name, title (if applicat	ole), and Name (Last, First and Title	e CARROLL, C.W. PROCESS ENGI		
business telephone number of t	the person			
to contact regarding information submitted on this form.	(607	(601) 134-3130		
		<u> </u>		
Dates of Waste Handling:				
Enter the years that you estima	te waste			
treatment, storage, or disposal t	pegan and From (Year)	50 To (Year) 1979		
ended at the site.				
•				
Waste Type: Choose the opt	ion you prefer to complete			
Option I: Select general waste you do not know the general was encouraged to describe the site	aste types or sources, you are	Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).		
General Type of Waste: Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.	Source of Waste: Place an X in the appropriate boxes.	Specific Type of Waste: EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is		
1. 🗷 Organics	1. □ Mining	located.		
2. X Inorganics	2. □ Construction			
3. Solvents	3. □ Textiles			
4. Pesticides	4. ☐ Fertilizer			
5. 🔀 Heavy metals	5. Paper/Printing			
6. ☐ Acids	6. Leather Tanning			
7. 🛪 Bases	7. Iron/Steel Foundry			
8. 🗖 PCBs	8. 🗆 Chemical, General			
9. Mixed Municipal Waste	9. Plating/Polishing			
10. 🗆 Unknown	10. Military/Ammunition			
11. ☐ Other (Specify)	11. Electrical Conductors			
	12. Transformers			
	13. Utility Companies	182177		
	14. ☐ Sanitary/Refuse	1		
	15. 🗆 Photofinish	I MADAN ARAN COMU NANA MADO DADO DADO DADO		
	16. ☐ Lab/Hospital			
	17. 🗆 Unknown			
	18. Other (Specify)			

Form Approved OMB No. 2000-0138 EPA Form 8900-1

	Notification of Hazardous Was te	Side Two				
F	Waste Quantity:	Facility Type	Total Facility Wast	e Amount		
	Place an X in the appropriate boxes to indicate the facility types found at the site.	1. ☐ Piles	cubic feet 4	H		
	In the "total facility waste amount" space	3. Land Treatment 3.	gallons			
	give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.	4. □ Tanks5. □ Impoundment	Total Facility Area			
	In the "total facility area" space, give the estimated area size which the facilities	6. ☐ Underground Injection7. ☐ Drums, Above Ground	acres			
	occupy using square feet or acres.	8. ☐ Drums, Below Ground 9. ★ Other (Specify)	PROCESSING/	RECYCLING		
G	Known, Suspected or Likely Releases to the Environment:					
	Place an X in the appropriate boxes to indicat or likely releases of wastes to the environment] Known □ Suspect	ted □ Likely □ None		
	Note: Items Hand I are optional. Completing hazardous waste sites. Although completing	these items will assist EPA and State and the items is not required, you are encouraged.	local governments in iged to do so.	locating and assessing		
H	Sketch Map of Site Location: (Optiona	1)		•		
	Sketch a map showing streets, highways, routes or other prominent landmarks near	en e		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	the site. Place an X on the map to indicate the site location. Draw an arrow showing					
	the direction north. You may substitute a publishing map showing the site location.					
		*				
			Market State			
	•					
				• . • • • • • • • • • • • • • • • • • •		
				} ******************************		
1	Description of Site: (Optional)					
	Describe the history and present					
	conditions of the site. Give directions to the site and describe any nearby wells,					
- ,	springs, lakes, or housing. Include such information as how waste was disposed			e e se se		
	and where the waste came from. Provide any other information or comments which	e e e e e e e e e e e e e e e e e e e				
	may help describe the site conditions.	•	•	tin the first of		
			. ,			
			•	and the second second		
				30 x 10 mm		
				11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
			•			
			•	A second of the second		
J	Signature and Title:		:			
	The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a	Name		Owner, Present		
		Street	•	☐ Owner, Past☐ Transporter☐ Operator, Present		
	mailing address (if different than address in item A). For other persons providing	City State	Zip Code			
	notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person	Julia	1:4	□ Operator, Past□ Other		
	required to notify. If you are not required to notify check "Other".	Signature Agnature V	CORECTED	النظام (الكانون بيراني أو الله الله الله الله الله الله الله الل		

yd G. Mount, Vice President



First Class Mail First Class Mail



CONTENTS -- MERCHANDISE

RETURN REQUESTED

US EPA Region 2 Sites Notification New York, NY 10007

CUSTOMER ORDER NO.

Ruetgers-Nease CHEMICAL COMPANY INC. STATE COLLEGE, PA. 16801



REFURN RECEIPT REQUESTED

P35 3778237

MAIL